

## Introduction

Thank you for choosing the QM10 from the Spectra Precision family of precision products. This easy-to-use distance measuring tool will allow you to measure distances quickly, accurately and reliably

Before using the Quick Measure, read this operator's manual carefully. Included is information about operation, safety and maintenance.

Ensure that the operating instructions are with the laser distance meter when it is given to other persons.


Your comments and suggestions are welcome; please contact us at:

Spectra Precision (USA) LLC 3265 Logistics Lane, Suite 200 Dayton, OH 45377 888-527-3771 (Toll Free) www.spectraprecision.com

-2-

# **Quick Start Guide**

# Power ON/OFF



Clear / Undo




Reference - Front / Rear




**Units Conversion** 



# Measure Single Distance



## **Continuous Measure**







# **Area Measurement**
















# Volume Measurement



















# Storage / Recall







\_9\_












# **Features**



Included with the QM10: Pouch, unit, batteries, user guide.



Features - LCD Detail




#### **Batteries - Installation**

- 1. Open the battery compartment using fingers or a coin.
- 2. Remove the batteries from the packaging and insert them in the tool.

NOTE When installing batteries note the positive (+) and negative (-) markings on the housings

Close the battery compartment cover.



Battery disposal - Some areas have regulations regarding the disposal of batteries. Be sure to dispose of discharged batteries properly.

CAUTION: The batteries should be removed when storing the laser more than 30 days.

-4-

### Features - LCD Detail

Icon	Name	Description
*	Laser on	Shows that laser is activated
* 1	Measure reference	Indicates measure reference from front or back
	Functions	Indicates functions: area, volume
	Battery indicator	More bars indicate more battery power remaining Flashing indicates it is time to change batteries
	Data storage	Indicates historical reading being displayed. 10 is most recent. 1 is the oldest.
Er000	Error Code	See Chart

-7-

# **General Operation**


# Single distance measurement

- 1) Switch on the device by pressing the ON button.
- 2) Press the ON button again to activate the laser.
- 3) Aim the laser do to the surface to be measured, and press the ON button again. The measurement will be shown in the display
- 4) Press and hold the OFF Button to switch off.

# Continuous measurement

- 1) With the device on, press and hold the ON Button for 2 seconds until the continuous measure icon appears to activate continuous measuring mode. The tool beeps during continuous measure mode.
- 2) Press the Measure Button again to stop continuous measure.
- When continuous measure is stopped, the display will show:
- · Maximum distance · Minimum distance
- · Last distance

Continuous measure can be useful to find the shortest distance to a wall or longest distance to a corner as shown.



Press the C/OFF button to clear the last reading or command. During area and volume measures, the C/OFF button clears the most recent measure, but preserves previous measures.

-8-

## Change reference

Clear button

Default measure reference is the back of the unit. With the device on, press the MEASURE REFERENCE and ON button to change to the front.

# Setting unit of measure


With the device on, press and hold OFF and FUNC buttons until the units of measure changes. Press again to change to next unit of measure. Unit of measure options are: m, ft, in, fractional inch (' ").

**-** 10 -- 12 -

# **FUNCTIONS - Area, Volume**



1) Press the FUNC button and cycle through the symbols until you arrive at the desired function as shown in this figure.



- 2) Press the ON button to activate the laser and take first measure
- 3) Press the ON button to activate the laser and take second measure
- Press the ON button to activate the laser and take third measure (if required)

The display will indicate which measure is being taken as per the following chart.

# FUNCTIONS - Area, Volume

Measurement Function	Icons	Measurement Sequence
Single Measurement	*	
Area Measurement		
Volume Measurement		

The result will be displayed along with the individual measures.

#### Storage and Recall of Measurements

The QM10 will automatically store the previous 10 measurement results.

- 1) To retrieve these measures: press the FUNC button three times.
- 2) Droop the ON button then proce the FUNC button
- 2) Press the ON button then press the FUNC button.

Press the FUNC button to cycle through the measurements

 The higher number (up to 10) indicates the most recent measurement taken.

**–** 15 **–** 



#### **Specifications**

Measuring Range	0.1 m to 30 m (0.3 to 100 ft)
Accuracy	± 2.0 mm typical (± 1/12 in)
Functions	Measure, Area, Volume, memory 10 measures
Measure reference	Front, Rear
Automatic shut off	Laser - 1 minute Product - 10 minutes
Battery life (alkaline)	8000+ measures
Power supply	2 x AAA x 1.5V
Power indication	LCD 3 segments
Operating temperature	-10°C to +40°C (14°F to 104°F)
Storage temperature	-20°C to +65°C (-4°F to 149°F)
Laser Safety	Class II as per EN 60825-1:2007; IEC 60825-1:2007 CFR 21 § 1040 (FDA)
Laser Type / Power	620-690 nm visible red / <1 mW max
Dimensions	43 x 24 x 110 mm (1.7 x 0.9 x 4.3 in)
Weight	74 g (2.6 oz) without batteries

**–** 16 **–** 

– 13 –

#### General Care, Safety And Storage

#### General safety rules

- a) Check the condition of the tool before use.
- b) The user must check the accuracy of the tool after it has been dropped or subjected to other mechanical stresses.
- c) Although the tool is designed for the tough conditions of jobsite use, as with other measuring instruments it should be treated with care.

# Do not use prisms or mirrored surfaces

Distances can be measured from all stationary targets without a highly reflective surface, i.e. concrete, stone, wood, plastic, paper, etc. The use of prisms or other highly reflective targets is not permissible and, if attempted, may falsify the results.

# **Calibration Check**

It is recommended to occasionally check the calibration of the tool.

- 1) Select a known measure distance about 1 to 5 meters (3 to 15 ft) that does not change over time.
- 2.) Measure the distance 10 times. Calculate the mean deviation from the actual distance. The measured mean deviation should be less than the typical accuracy tolerance of  $\pm$  2.0 mm ( $\pm$  1/12 in)

# Cleaning and drying

- 1. Blow dust off the lens.
- 2. Do not touch the lens with the fingers.
- 3. Use only a clean, soft cloth for cleaning. If necessary, moisten the cloth slightly with pure alcohol or a little water.

\_ 14 \_

**NOTE** Do not use any other liquids as these may damage the plastic components.

# Storage

The temperature limits for storage of your equipment must be observed, especially in winter / summer.

Remove the tool from its pouch if it has become wet. The tool, its carrying case and accessories should be cleaned and dried (at maximum 40°C). Repack the equipment only once it is completely dry. Check the accuracy of the equipment before it is used after a long period of storage or transportation.

#### **Transport**

Use the original packaging or packaging of equivalent quality for transporting or shipping your equipment.

# CAUTION

Always remove the batteries before shipping the tool.

Trouble Shooting

Message Code	Possible cause	Remedy
err101	Battery too low	Change batteries
err154	Out of range	Measure target within distance of 0.1 and 30 m (0.3 to 100 ft)
err156	Received signal too weak	Use light color target;
err194	Ecceeding the numerical display range	

– 17 –

# Laser Safety

Use of this product by people other than those trained on this product may result in exposure to hazardous laser light.

- Do not remove warning labels from the unit.
- The QM10 is a Class 2M (620-690 nm) laser product
- Never look into the laser beam or direct it to the eyes of other people.
- Always operate the unit in a way that prevents the beam from getting into people's eyes.



Warranty

Spectra Precision LLC warrants the Quick Measure QM10 to be free of defects in material and workmanship for a period of 1 year. This warranty period is in effect from the date the system is delivered by Spectra Precision LLC or its authorized Dealer to the purchaser, or is put into service by a Dealer as a demonstrator or rental component.

**- 18 -**

Any evidence of negligent or abnormal use, or any attempt to repair equipment by other than factory-authorized personnel or Spectra Precision LLC certified or recommended parts, automatically voids the warranty.

The foregoing states the entire liability of Spectra Precision LLC regarding the purchase and use of its equipment. Spectra Precision LLC will not be held responsible for any consequential loss or damage of any kind.

This warranty is in lieu of all other warranties, except as set forth above, including an implied warranty. Merchantability of fitness for a particular purpose is hereby disclaimed.

Customers should send products to the nearest authorized Factory, Dealer or Service Center for warranty repairs, freight prepaid. In countries with Spectra Precision LLC Service Subsidiary Centers, the repaired products will be returned to the customer, freight prepaid.

**Request for Service** 

To locate your local dealer or authorized Spectra Precision Service Center outside the U.S.A for service, accessories, or spare parts, contact one of our offices listed below or www.spectraprecision.com.

- 19 -

- 23 -

North & Latin America

Spectra Precision 3265 Logistics Lane, Suite 200 Dayton, Ohio 45377 U.S.A. (888) 527-3771 (Toll Free)

Europe, Africa & Middle East Spectra Precision (Kaiserslautern) GmbH Am Sportplatz 5 67661 Kaiserslautern GERMANY Tel +49-(0)6301-71 14 14 Fax +49-06301-32213 - 20 -

#### Declarations

We declare, on our sole responsibility, that this product complies with the following directives and standards:

EN 50081-1, EN 61000-6-2, 2004/108/EC.

Designation: Laser range meter

Type: QM10

#### **Protecting the Environment**

The unit, accessories and packaging ought to be recycled.

All plastic parts are marked for recycling according to material type.



Do not throw used batteries into the garbage, water or fire. Remove them in compliance with environmental requirements.





© 2023, Spectra Precision (USA) LLC. All rights reserved. Reorder PN 1213-3120 Rev B (05/23)

- 21 - - 22 -